L Street Compound Grants Pass, Oregon



Building 2101 – Warehouse Shop



Panorama Looking Northwest – L to R –Buildings 2205, 2309, 2101.



Panorama looking East – L to R Buildings 2310 and 2206.



Gas House, Building 2501



Inspector's Shack - Building 2007



Inside Warehouse -Shop




Typical Inside of Warehouse



Entrance Gate on L Street



North end of property looking Northeast toward wash rack with Building 2101 on right



Detail of Building 2101 –Warehouse-Shop with pine tree motif



Windows and pine tree motif on west side of Warehouse-Shop Bldg 2101